BUILDING SAFETY CERTIFICATE

	No. Dated: 16.05.2023
	Certified that the existing building
	Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes
	conditions as appended. 1. Building is mentarined 2. Boundaies near be made more secured. 3. The Roof may be cleaned before monsoon. 4. Mangement shall ensure nowalin stagnation in the Campus. keep the chainoft of Stagnation in the Campus.
WHIT	*Strike out whichever is not applicable. Signature with Seal: Name: Designation: LC BELWAL Manager Public Works Department Warner Strike out whichever is not applicable. Name: Designation: LC BELWAL Manager Public Works Department Warner Strike out whichever is not applicable.
	Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only The filled up certificate should be either in Hindl or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf. The observations are based on building Safety certificate issued by

Structural Engineer. OF MIS MUP consultant Haldwani.

(J. c Belowd)

M.V.P. Consultants & Associates

Valuer of Fixed Assets, Architectural and Structural Design, Authorised Structure Engineer, Consultant for Hydro Power Projects, Environment and Pollution Control and Environmental Impact Assessment

OFFICE: 203, TARA PLACE, NAINITAL ROAD, HALDWANI - 263139 (NAINITAL) UK

Ref. No. YOU MYPOLL 5006

Dated...16|05|2023

BUILDING SAFTY CERTIFICATE

Construction of School Building at Aanpur Nawar, Teh.- Haldwani, Distt.- Nainital

- 1. Name of school White Hall
- 2. Name of owner 1)- Smt. Madhu Lal, 2)- Sh. Rajiv Lal

General

The owners of White Hall School at Lamachuar, Teh- Haldwani, Distt. Nainital, desired to have structural stability aspect of the building. The building was inspected on 06/05/2023. The building is a triple storey framed structure made in three blocks in a shape of cul-de-sec. The building has classrooms, toilets for boys and girls, administrative rooms etc and connected with a corridor in front of each floor. The plinth of building is kept at 90 cm. from natural ground level. This is important because the area has a tendency of flooding during monsoon.

The building was examined in detail from structural aspects. The reinforcement and the depth of foundation checked as per designs and drawings provided by owner. Columns reinforcement was exposed at roof and found to be as per design. Adequate slab thickness resting on beams are stable. No differential settlement was observed in beams and walls. The building is free from any seepage, leakage and minor cracks. Building is well maintained and fit to use.

Enclose- 1) Detail design of structural elements.

Photographs of building.

Mahager WHITEHALL SCHOOL

WHITEHAL 8CH

Principa

Er. HARIT VERMA
Structural Engg.
(For M.V.P. Consultant & Associates)

* ALDINE TO

E-mail: consultantmvp@gmail.com

Contact No.: 05946-222990, 9837048074













SITE PHOTOGRAPHS OF PROPERTY BELONGS TO WHITE HALL SCHOOL AT VILLAGE AANPUR NAWAR LAMACHAUR, TEH- HALDWANI, DISTT. NAINITAL.

Manager WHITEHALV SCHOO! Hall-bani

Er. HARIT VERMA
Structural Engg.
(For M.V.P. Consultant & Associates)



